



**View of the Magnolia tree (behind the house) from the street (Cul de sac)**



**View of the subject tree from the sideyard**



**Damage to Concrete slab Patio below the Magnolia tree**